



Notice is hereby given that the  
**Eastern Summit County Sewer Advisory Committee (ESAC)**  
will meet on  
**Thursday, January 10, 2019**  
**8:00 a.m.**

Summit County Courthouse, Conference Room 2A & B  
60 N. Main Street, Coalville, UT

### **AGENDA**

1. Public input not on the agenda
2. Discussion and possible recommendation for the proposed Wastewater Treatment for Eagle Watch LLC 2 lot subdivision, Parcel CD-222-A, Peoa. Mark Longshore, applicant.– Jennifer Strader, Senior Planner
3. Discussion and possible recommendation for the proposed Wastewater Treatment for Stephen Kladis 2 lot subdivision, Parcel CD-222-A-1, Peoa. –Jennifer Strader, Senior Planner
4. Approval of Minutes: October 25, 2018

*Individuals with questions, comments, or needing special accommodations pursuant to the Americans with Disabilities Act regarding this meeting may contact Susan Ovard in the Community Development Department at (435) 336-3126.*

Posted: January 4, 2019  
Published: January 4, 2019





















# SUMMIT COUNTY HEALTH DEPARTMENT

## Percolation Test and Soil Evaluation Results Form

Test Requested By: Steve Kladis Date: 11/5/2018 Tax ID # CD-222-A PAI

Property Address: 1945 W. STATE RD 32 Subdivision: \_\_\_\_\_  
 Lot# 222-A-PAR Soak Start Date/Time: 11:30 11/4/2018 Soak End Time: 3:30

Percolation results shall be valid for two years from date of test. Percolation tests shall be performed according to Appendix D of R317-4. Summit County Requires a minimum of 4 measurements. Measurements must be 30 min apart unless 6 inches of water seeps away in less than 30 minutes then measurements can be taken at 15 min intervals.

Start Time	Measurement	End Time	Measurement	Change in level	Perc Rate min/inch
11:16	6 1/8"	12:26	7 1/8"	1"	10MPI
11:26	6 1/8"	11:36	7 1/8"	1"	10mpi
11:37	6 1/8"	11:47	7 1/8"	1"	10mpi
11:48	6 1/8"	11:58	7 1/8"	1"	10mpi

Final Stabilized Percolation Rate: 10mpi min/inch. Depth of water table: n/a ft.  
 Depth of highest anticipated groundwater: n/a ft. Depth to bedrock: n/a ft.

### Soil Evaluation

Depth	Soil Type
0 - 24"	Topsoil
24" - 72"	Sandy Clay Loam - WHITE
72" - 120"	Sandy Clay Loam - W/ Cobble and gravel

*By Signing this Document I am stating that the perc test was completed in accordance to R317-4 Utah Onsite Wastewater Systems.*

Print Name: Andy Bailey Certification # 000598-OSP-1

Signature of Certified Tester: 

E-mail Address: andy@bluegrassx.com Phone # 435.640.5676

COALVILLE OFFICE  
 85 North 50 East, PO Box 128  
 Coalville, UT 84017  
 435-336-3234

PARK CITY OFFICE  
 650 Round Valley Drive  
 Park City, UT 84060  
 435-333-1500